


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 01/95 To (mo./yr.) 12/95
2. DOGM File Number (Mine No): S / 27 / 056
3. Mine Name: Miller Cove/Split Rock/Bright Lite 7&8
4. Mineral(s) Mined (or permitted to mine): Precious Metals
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
NW 1/4, SE 1/4, Section 12, Township 19, Range 14
SE 1/4, SE 1/4, Section 12, Township 19, Range 14
SW 1/4, SE 1/4, Section 12, Township 19, Range 14
7. Name of Operator or Company: Nielson Mining
8. Permanent Street Address: 3900 S Redwing Street
City, State, Zip: West Valley, Utah 84119-4521
Phone: hm 801 969 1863 cell 801 599 6773
9. Company Representative (or designated operator):
Name: Marion K. Nielson
Title: Partner
Business Address: 3900 S Redwing Street
City, State, Zip: West Valley, Utah 84119-4521
Phone: hm 801 969 1863 cell 801 599 6773
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 112 grams of placer gold

3. How much **additional** acreage was disturbed during the past year? Sporadic less than one acre.
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
- Excavated one trench approx three feet by two feet and
from one foot to six feet deep on Split Rock location.
Approx five hundred yards of material was excavated on
Bright Lite 7. Approx fifty yards was sluiced.
5. How much acreage was **reclaimed** during the past year? Trench left open. Approx 75% of Bright Lite reclaimed.
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
- Previous mounds and diggings were leveled to extent possible.
This is ongoing. Results and evaluations are adequate.
7. What is the total disturbed acreage at years end? Sporadic less than one acre.
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
- Additional sluicing of material on Bright Lite. Mined areas
will be refilled and leveled with materials processed.
Additional exploration and testing in trenched area.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Marion K. Nielson

Title of Operator:

Partner

Signature of Operator:

Marion K. Nielson

Date:

28 Jan 1996



Marion (Ken) Nielson
3900 Redwing St. (801) 969-1863
West Valley City, UT. 84119 Cell. 599-6773
